

In-Production Photo Report for

Borough of Totowa, NJ

Job# 39836

Status as of October 03, 2025

In this report the cab began fabrication, the frame build began, the pump house began initial assembly, and the body began the fabrication process. In the next report the cab may continue fabrication, the frame build may continue, the pump house may continue initial assembly, and the body may complete the fabrication process and be staged.



For valued customers of





DSC03149



DSC03150



DSC03151



DSC03152



DSC00150



DSC00151



DSC00152



DSC00153



DSC00154



DSC00155



DSC00156




DSC00157



DSC00158



DSC00159



DSC00160



DSC00161



DSC00162



DSC03087



DSC03088




DSC03089




DSC03090



DSC03091



DSC03115



DSC03116



DSC03117



DSC03118



DSC03119