

In-Production Photo Report for Borough of Totowa, NJ Job# 39836


Status as of October 24, 2025

In this report the cab completed paint and began initial assembly, the frame build continued, the pump house remained staged, and the body continued through paint. In the next report the cab may continue initial assembly, the frame build may continue, the pump house may remain staged, and the body may continue the paint process.



For valued customers of





DSC06128



DSC06129



DSC06130



DSC06131



DSC06132



DSC06231




DSC06232



DSC06233



DSC06234



DSC06235



DSC06236



DSC06237



DSC06238




DSC06266



DSC06267



DSC06268



DSC06282



DSC06283



DSC06284



DSC06285



DSC06286