

In-Production Photo Report for Borough of Totowa, NJ Job# 39836


Status as of October 17, 2025

In this report the cab began the paint process, the frame build continued, the pump house completed initial assembly, and the body began the paint process. In the next report the cab may complete the paint process, the frame build may continue, the pump house may remain staged, and the body may continue through paint.



For valued customers of





DSC00157



DSC00158



DSC00159



DSC00160



DSC00161



DSC00105



DSC00106



DSC00107



DSC00108



DSC00109



DSC00154



DSC00155



DSC00156



DSC00900



DSC00901



DSC00902



DSC00903



DSC00904