


In-Production Photo Report for Borough of Totowa, NJ Job# 39836

Status as of October 10, 2025

In this report the cab completed fabrication, the frame build continued, the pump house was painted then staged to continue initial assembly, and the body completed fabrication. In the next report the cab may be staged to begin the paint process, the frame build may continue, the pump house may continue initial assembly, and the body may be staged to begin the paint process.



For valued customers of



DSC03185



DSC03186



DSC03187



DSC00091



DSC00092



DSC00093



DSC00094



DSC00095



DSC03080



DSC03081




DSC03082



DSC03083



DSC03084



DSC03058



DSC03059



DSC03060



DSC03061



DSC03062