

In-Production Photo Report for Borough of Totowa, NJ Job# 39836


Status as of October 31, 2025

In this report the cab, pump house, and body were merged with the frame at the start of initial apparatus assembly. In the next report your apparatus may begin final assembly.



For valued customers of





DSC00368



DSC00369



DSC00370



DSC00371



DSC00372




DSC00373



DSC00374




DSC00375



DSC00376



DSC00377



DSC00378



DSC00379



DSC00380



DSC00381



DSC00382



DSC00383



DSC00384



DSC00385



DSC00386



DSC00387



DSC00388



DSC00389



DSC00390



DSC00391



DSC00392



DSC00393



DSC00394



DSC00395



DSC00396



DSC00397



DSC00398



DSC00399



DSC00400



DSC00401



DSC00402




DSC00403



DSC00404



DSC00405



DSC00406



DSC00407



DSC00408



DSC00409



DSC00410



DSC00411



DSC00412




DSC00413



DSC00414



DSC00415



DSC00416



DSC00417



DSC00418



DSC00419



DSC00420



DSC00421



DSC00422



DSC00423



DSC00424



DSC00425



DSC00426



DSC00427



DSC00428



DSC00429



DSC00430



DSC00431



DSC00432



DSC00433



DSC00434



DSC00435



DSC00436



DSC00437



DSC00438



DSC00439



DSC00440



DSC00441



DSC00442



DSC00443



DSC00444



DSC00445



DSC00446



DSC00447



DSC00448




DSC00449



DSC00450



DSC00451



DSC00452



DSC00453



DSC00454



DSC00455



DSC00456



DSC00457



DSC00458



DSC00459



DSC00460



DSC00461



DSC00462